



Reduce Chip Inventory & Save With HP / Canon Universal Chips



U1-2 Series		U3-2 Series		U3-2 Drum Unit		U4-2 Series		U5-2 Series	
<u>Part #:</u> 05-U1-2CP-KBAG50 05-U1-2CP-CBAG50 05-U1-2CP-MABAG50 05-U1-2CP-YBAG50		<u>Part #:</u> 05-U3-2CHIP-C 05-U3-2CHIP-MA 05-U3-2CHIP-Y		<u>Part #:</u> 05-U3-2CHIP-DU10		<u>Part #:</u> 05-U4-2CHIP-KBAG50 05-U4-2CHIP-CBAG50 05-U4-2CHIP-MABAG50 05-U4-2CHIP-YBAG50		<u>Part #:</u> 05-U5-2CHIP-BAG50	
<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>
HP1500/2500 K	C9700A	HP2550,2820/2840 K	Q3960A	HP1500/2500	C9704A	HP4600/4650 K	C9720A	HP4100	C8061X
HP1500/2500 C	C9701A	HP2550,2820/2840 C	Q3961A	HP2550,	Q3964A	HP4600/4650 C	C9721A	HP9000/9050	C8543X
HP1500/2500 M	C9703A	HP2550,2820/2840 M	Q3963A	HP2820 / 2840	EP-87	HP4600/4650 M	C9273A		
HP1500/2500 Y	C9702Y	HP2550,2820/2840 Y	Q3962A	Canon LBP 2410	As Above	HP4600/4650 Y	C92722A		
HP2550,2820/2840 K	Q3960A	HP3500 / 3550 C	Q2671A	MF8170 / 8180	101,301 701	HP5500/5550 K	C9730A		
HP2550,2820/2840 C	Q3961A	HP3500 / 3550 M	Q2673A	Canon LBP 5200	As Above	HP5500/5550 C	C9731A		
HP2550,2820/2840 M	Q3963A	HP3500 / 3550 Y	Q2672A			HP5500/5550 M	C9733A		
HP2550,2820/2840 Y	Q3962A					HP5500/5550 Y	C9732A		
HP3500 / 3550 K	Q2670A					Canon LBP 2510	EP-85		
HP3700 K	Q2670A					Canon LBP 2710	EP-86		
HP3700 C	Q2681A					/5700	As Above		
HP3700 M	Q2683A								
HP3700 Y	Q2682A								
Canon LBP 2410,	EP-87								
MF8170 / 8180									
Canon LBP 5200	101,301 701								

Imaging Solutions (Australasia)

Ph: 1300 88 37 40 International: 61 3 9587 7788
 Melbourne: Fax: 61 3 9580 4497 Sydney: Fax: 61 2 9999 0744



Reduce Chip Inventory & Save With HP / Canon Universal Chips



U14-2 Series		U15-2 Series		U16		U17-3 Low Yield		U18-3 High Yield	
<u>Part #:</u> 05-U14-2CHIP-C50 05-U14-2CHIP-MA50 05-U14-2CHIP-Y50		<u>Part #:</u> 05-U15-2CHIP-K50 05-U15-2CHIP-C50 05-U15-2CHIP-MA50 05-U15-2CHIP-Y50		<u>Part #:</u> 05-U16CHIP		<u>Part #:</u> 05-U17-3CHIP		<u>Part #:</u> 05-U18-3CHIP	
<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>
HP3600 C	Q6471A	HP1600	Refer Below	HP 5200	Q7516A	Canon LBP 3300	CART308	Canon LBP 3300	CART308II
HP3600 M	Q6473A	HP2600/2605 K	Q6000A	HP M5025/5035	Q7570A	Canon LBP 3310	CART315	Canon LBP 3310	CART315II
HP3600 Y	Q6472A	HP2600/2605 C	Q6001A	Canon LBP 3500/ 3900/3950	309, 509 As Above	Canon LBP 3360	CART708	Canon LBP 3360	CART708H
HP CP4005 K	CB400A	HP2600/2605 M	Q6003A			HP1160/1320	Q5949A	HP1300	Q2613X
HP CP4005 C	CB401A	HP2600/2605 Y	Q6002A			HP1300	Q2613A	HP1320	Q5949X
HP CP4005 M	CB403A	HP2700/3000 K	Q7560A			HP2300	Q2610A	HP2300	Q2610A
HP CP4005 Y	CB402A	HP2700/3000 C	Q7561A			HP2400 Series LY	Q6511A	HP2400 Series HY	Q6511X
		HP2700/3000 M	Q7563A			HP3390/3392	Q5949A	HP3390/3392	Q5949X
		HP2700/3000 Y	Q7562A			HP4200	Q1338A	HP4200	Q1338A
		HP3600 K	Q6470A			HP P2015	Q7553A	HP4250 / 4350 HY	Q5942X
		HP3800 K	Q6470A			HP P3005 / 3027 & 3035	Q7551A As Above	HP4300	Q1339A
		HP3800 C	Q7581A			HP4250 / 4350 & 4240	Q5942A As Above	HP4345 / M4345	Q5945A
		HP3800 M	Q7583A					HP P2015	Q7553X
		HP3800 Y	Q7582A					HP P3005 / 3027 & 3035	Q7551X As Above
		HP4700 K / C / M / Y	Various						
		HP4730 K / C / M / Y	Various						
		Canon LBP 5000 / 5100	CART307 K/C/M/Y						
		HP CP3505 K	Q3470A						
		HP CP3505 C	Q7581A						
		HP CP3505 M	Q7583A						
		HP CP3505 Y	Q7582A						

Imaging Solutions (Australasia)

Ph: 1300 88 37 40 International: 61 3 9587 7788

Melbourne: Fax: 61 3 9580 4497 Sydney: Fax: 61 2 9999 0744



Reduce Chip Inventory & Save With HP / Canon Universal Chips



U23 Starter		U24 Low Yield		U25 High Yield		U26 Intro & Low Yield		U27 High Yield	
<u>Part #:</u> 05-U23-CHIP * Info. below relates to Starter/Intro Cart's ONLY		<u>Part #:</u> 05-U24-CHIP		<u>Part #:</u> 05-U25-CHIP		<u>Part #:</u> 05-U26-CHIP-K 05-U26-CHIP-C 05-U26-CHIP-MA 05-U26-CHIP-Y		<u>Part #:</u> 05-U27-CHIP-K 05-U27-CHIP-C 05-U27-CHIP-MA 05-U27-CHIP-Y	
<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>
Canon LBP 3050	CART312	Canon LBP 3050	CART312	Canon LBP 3050	CART312	Canon LBP 5050 K	CART316BK	Canon LBP 5050 K	CART316BK
Canon LBP 3100	CART312	Canon LBP 3100	CART312	Canon LBP 3100	CART312	Canon LBP 5050 C	CART316C	Canon LBP 5050 C	CART316C
Canon LBP 3150	CART312	Canon LBP 3150	CART312	Canon LBP 3150	CART312	Canon LBP 5050 M	CART316M	Canon LBP 5050 M	CART316M
Canon LBP 3250	CART313	Canon LBP 3250	CART313	Canon LBP 3250	CART313	Canon LBP 5050 Y	CART316Y	Canon LBP 5050 Y	CART316Y
HP M 1120 MFP	CB436A	HP M 1120 MFP	CB436A	HP P 2055	CE505X	Canon LBP 7200 K	CART318BK	Canon LBP 7200 K	CART318BK
HP M 1522 MFP	CB436A	HP M 1522 MFP	CB436A	HP P 4015	CC364X	Canon LBP 7200 C	CART318C	Canon LBP 7200 C	CART318C
HP P 1005	CB435A	HP P 1005	CB435A	HP P 4515	CC364X	Canon LBP 7200 M	CART318M	Canon LBP 7200 M	CART318M
HP P 1006	CB435A	HP P 1006	CB435A			Canon LBP 7200 Y	CART318Y	Canon LBP 7200 Y	CART318Y
HP P 1505	CB436A	HP P 1505	CB436A			HP CM 3530	CE250A	Canon MF 8050	CART416K/C/M/Y
		HP P 2035	CE505A			HP CM 2320 K	CC530A	HP CP 1215/1515/	CB540A
		HP P 2055	CE505A			HP CM 2320 C	CC531A	1518/ CM 1312	CB541A
		HP P 4014	CC364A			HP CM 2320 M	CC533A		CB543A
		HP P 4015	CC364A			HP CM 2320 Y	CC532A		CB542A
		HP P 4515	CC364A			HP CP 1215 /	CB540A Intro	HP CP 2025 / HP	CC530A
						1515 / 1515 /	CB541A Intro	CM 2320	CC531A
						CM 1312	CB543A Intro		CC533A
							CB542A Intro		CC532A
						HP CP 2025 K	CC530A	HP CP 3525 / HP	CE250X
						HP CP 2025 C	CC531A	CM 3530	CE251A
						HP CP 2025 M	CC533A		CE253A
						HP CP 2025 Y	CC532A		CE252A
						HP CP 3525 K	CE250A		

Imaging Solutions (Australasia)

Ph: 1300 88 37 40 International: 61 3 9587 7788
Melbourne: Fax: 61 3 9580 4497 Sydney: Fax: 61 2 9999 0744



Reduce Chip Inventory & Save With HP / Canon Universal Chips



U29		U30 Starter & Intro							
<u>Part #:</u> 05-U29-CHIP		<u>Part #:</u> 05-U30-CHIP *Info. below relates to Starter/Intro Cart's ONLY		<u>Part #:</u>		<u>Part #:</u>		<u>Part #:</u>	
<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>
Canon LBP 3050	CART312	Canon IC D1120	CART320						
Canon LBP 3150	CART312	Canon IC D1150	CART320						
Canon LBP 3250	CART313	Canon IC D1170	CART320						
Canon LBP 6000	CART325	Canon IC D1180	CART320						
HP M 1132	CE285A	Canon LBP 6000	CART325						
HP M 1212 MFP	CE285A	HP M 1132	CE285A						
HP M 1120	CB436A	HP M 1212 MFP	CE285A						
HP M 1522	CB436A	HP P 1102	CE285A						
HP P 1005	CB435A	HP P 1566	CE278A						
HP P 1006	CB435A	HP P 1606	CE278A						
HP P 1102	CE285A								
HP P 1505	CB436A								
HP P 1566	CE278A								
HP P 1606	CE278A								

Imaging Solutions (Australasia)

Ph: 1300 88 37 40 International: 61 3 9587 7788
 Melbourne: Fax: 61 3 9580 4497 Sydney: Fax: 61 2 9999 0744



Reduce Chip Inventory & Save With



IBM / Lexmark / Dell / Toshiba Multi Brand Chips

E 321 Series		T 430 Series		T 520 Series		T 630 Series		T 630 Series	
Part #: 05-LE321CHIP-MBC50 (6K)		Part #: 05-LT430CHIP-MBC50 (12K)		Part #: 05-LT520CHIP-MBC50 (30K)		Part #: 05-LT620CHIP-MBC50 (30K)		Part #: 05-LT630CHIP-MBC50 (21K)	
<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>
Dell P 1500		IBM InfoP 1422		IBM InfoP 1120		IBM InfoP 1130	28P2010	Dell M 5200N	
IBM InfoP 1312	75P4684	IBM InfoP 1422D		IBM InfoP 1125		IBM InfoP 1140	28P2010	Dell W 5300N	
Lexmark E321	12A7305	IBM InfoP 1422DN		Lexmark T520	12A6835	Lexmark T620	12A6865	Dell W 5300N	
Lexmark E323	12A7305	Lexmark T430	12A8425	Lexmark T522	12A6835	Lexmark T622	12A6865	IBM InfoP 1332	75P4303
Lexmark E323 N	12A7305	Lexmark T430D	12A8425	Lexmark X520 MFP		Source Tech ST 9130 MICR		IBM InfoP 1352	75P4305
Lexmark E323 T	12A7305	Lexmark T430DN	12A8425	Source Tech ST 9120 MICR		Source Tech ST 9140 MICR		IBM InfoP 1372	75P4305
Source Tech T 9216 MICR		Soure Tech ST 9420 MICR		Source Tech ST 9125 MICR		Toshiba E-Studio 30 P		Lexmark T630	12A7462
				Toshiba E-Studio 20 P		Toshiba E-Studio 40 P		Lexmark T632	12A7462
				Toshiba E-Studio 25 P				Lexmark T634	12A7462
								Lexmark X630 MFP	
								Lexmark X632 MFP	
								Lexmark X634 MFP	
								Source Tech ST 9325 MICR	
								Source Tech ST 9335 MICR	
								Source Tech ST 9340 MICR	
								Toshiba E-Studio 400 P	

Imaging Solutions (Australasia)

Ph: 1300 88 37 40 International: 61 3 9587 7788

Melbourne: Fax: 61 3 9580 4497 Sydney: Fax: 61 2 9999 0744



Reduce Chip Inventory & Save With



IBM / Lexmark / Dell / Toshiba Multi Brand Chips

T 634 Series		T 640 Series		T 644 Series		X 342 Series		X 422 Series	
<u>Part #:</u> 05-LT634CHIP-MBX50 (32K)		<u>Part #:</u> 05-LT640CHIP-MBC (21K)		<u>Part #:</u> 05-LT644CHIP-MBXC (32K)		<u>Part #:</u> 05-LX342CHIP-MBC50 (6K)		<u>Part #:</u> 05-LX422CHIP-MBC50 (12K)	
<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>	<u>For these Printers:</u>	<u>Cart Part#:</u>
Dell M 5200N Dell W 5300N Dell W 5300N IBM InfoP 1332 IBM InfoP 1352 IBM InfoP 1372 Lexmark T630 Lexmark T632 Lexmark T634 Lexmark X630 MFP Lexmark X632 MFP Lexmark X634 MFP Source Tech ST 9325 MICR Source Tech ST 9335 MICR Source Tech ST 9340 MICR Toshiba E-Studio 400 P	75P4303 75P4305 75P4305 12A7462 12A7462 12A7462	Dell 5210N Dell 5310N Dell 5310N IBM InfoP 1532 Express IBM InfoP 1552 IBM InfoP 1552N IBM InfoP 1572 Lexmark T640 Lexmark T642 Lexmark T644 Lexmark X642E MFP Lexmark X644E MFP Lexmark X646DTE MFP Lexmark X646E MFP Source Tech ST 9530 MICR Source Tech ST 9550 MICR	64017HR 64017HR 64017HR	Dell 5210N Dell 5310N Dell 5310N IBM InfoP 1532 Express IBM InfoP 1552 IBM InfoP 1552N IBM InfoP 1572 Lexmark T642 Lexmark T644 Lexmark X642E MFP Lexmark X644E MFP Lexmark X646DTE MFP Lexmark X646E MFP Source Tech ST 9530 MICR Source Tech ST 9550 MICR	64017HR 64017HR 64017HR	Dell 1700/N Dell 1710N IBM InfoP 1412 IBM InfoP 1512 Lexmark E230 Lexmark E232 Lexmark E234 Lexmark E238 Lexmark E240 Lexmark E330 Lexmark E332N Lexmark E340 Lexmark E342N Lexmark X340 MFP Lexmark X342N MFP Toshiba E-Studio 270P Toshiba E-Studio 300P Source Tech ST 9410 MICR Source Tech ST 9510 MICR	75P5711 34217HR 34217HR	IBM InfoP 1410 MFP Lexmark X422 MFP	12A4715

Imaging Solutions (Australasia)

Ph: 1300 88 37 40 International: 61 3 9587 7788

Melbourne: Fax: 61 3 9580 4497

Sydney: Fax: 61 2 9999 0744